

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2018-05-11	TECHNICIAN Darren Mann		JOB/ORDER # 8474		REFERENCE TEXT 18-0629
FIRST NAME Advent		LAST NAME Admin	7		
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 505 - 1225 RICHARDS ST, BUZ#1505 MANYA: 604.308.4620 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.6478				EMAIL andrea@adventvancouver.com	

REASON FOR TODAY'S CALL: Kitchen sink drain blockage

DESCRIPTION OF WORK PERFORMED:

The kitchen sink drain blockage was caused by food debris. The garburator grinding chamber is deteriorating to the point that bits of the spinning disc are flaking off, allowing larger pieces of food to pass through and in turn clog up the drain. I replaced the garburator with new, and tested by filling and draining the sink multiple times while running the garburator.

QTY. CODE		DESCRIPTION		PRICE	
1	Supply & Install 1/2HP Waste King 1001 Garburator				\$279.00
Give us F	WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTI MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT M		SUBTOTAL:	\$279.00
Please visit our feedback				GST (5%):	\$13.95
www.yaletownplumbing.o	s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$292.95	
invoice and tell us how w	MATERIALS LIS	RVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND TH STED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RES TED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS / OM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. ASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATE O. E.	PONSIBLE FOR BROKEN, AND ANY OTHER DAMAGES		