

🕒 @SimplyPlumbing 🛛 🚹 YaletownPlumbing

HST #837181627

DATE 2018-05-15	TECHNICIAN Darren Mann		JOB/ORDER # 8482		REFERENCE TEXT Client reference
FIRST NAME George		LAST NAME Fedeas			
BILLING ADDRESS COMPANY / BILLING NAME 212 - 2201 PINE ST VANCOUVER, V6J5E7 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 212 - 2201 PINE ST BUZ212 VANCOUVER, V6J5E7 BRITISH COLUMBIA, CANADA	
PHONE 604.731.1728				EMAIL Gpfwrx@telus.net	

REASON FOR TODAY'S CALL:

Toilet tank malfunction; after flushing, water doesn't flow back into tank though valve is on. When tank floater is 'jiggled' flow begins but is incredibly slow.

DESCRIPTION OF WORK PERFORMED:

I replaced the FillValve and supply line and tested by flushing multiple times. Toilet is now in good working order.

QTY .	CODE			DESCRIPTION	UNIT PRICE	PRICE
1		Replace toilet FillValve - standard				\$159.00
Gue us Geedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.95	
		INTEREST AT	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$166.95	
		SETTLED, RU RESULTING F	ISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, ISTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK & O. E. DIB-05-15 CUSTOMER SIGNATURE DATE			