

HST #837181627

DATE 2018-05-16	TECHNICIAN Darren Mann		JOB/ORDER # 8456		REFERENCE TEXT Client reference
FIRST NAME Lawrence		LAST NAME Ng			
BILLING ADDRESS HJ WU & COMPANY INC 303 - 1409 WEST PENDER ST VANCOUVER, V6G 2S3 BRITISH COLUMBIA, CANADA			303 VAN	VICE ADDRESS - 1409 WEST PENDER S COUVER, V6G 2S3 FISH COLUMBIA, CANAC	
PHONE 604-636-1862			EMA bcte	NL chnology@gmail.com	

REASON FOR TODAY'S CALL: toilet running. \*clicking noise

## **DESCRIPTION OF WORK PERFORMED:**

-Master Bathroom: I replaced the flushvalve gasket and cleaned out the diaphragm in the fillvalve. Tested and in good working order. -Guest Bathroom: I believe the clicking noise reported is coming from the vent.

QTY.	CODE	DESCRIPTION				PRICE
1	//	Replace FlushValve Gasket - Geberit In-Wall			\$149.00	\$149.00
		ARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$149.00	
				LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.45
			10	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$156.45
			THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND			

<u> Thank You!</u>

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2018-05-16

CUSTOMER SIGNATURE

DATE