



HST #837181627

DATE 2018-05-17	TECHNICIAN Darren Mann		JOB/ORDER # 8487		REFERENCE TEXT Client reference	
FIRST NAME Kathryn		LAST NAME Neal	707			
BILLING ADDRESS COMPANY / BILLING NAME 2505 - 1438 RICHARDS ST. VANCOUVER, V6Z 3B8 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 2505 - 1438 RICHARDS ST., VANCOUVER, V6Z 3B8 BRITISH COLUMBIA, CANAD		
PHONE 604.230.0185				EMAIL Rehmkathryn@gmail.com		

REASON FOR TODAY'S CALL:

Tub faucet drips constantly.

DESCRIPTION OF WORK PERFORMED:

I replaced the mixing(HC180) and pressure balance cartridges within the shower valve and tested.

QTY.	CODE		DESCRIPTION			
1		Replace Mixing & Pressure E	e Mixing & Pressure Balance Cartridge - HC180			
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		warranty	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$219.00	
			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	GST (5%):	\$10.95	
		ls from your		TOTAL:	\$229.95	

<u> Thank You!</u>

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES, E. & O. E.

2018-05-17

CUSTOMER SIGNATURE

DATE