

HST #837181627

DATE 2018-05-18	TECHNICIAN Darren Mann		JOB/ORDER # 8475	REFERENCE TEXT Client reference
FIRST NAME Hyun Ju (Stephanie)		LAST NAME Lee		
BILLING ADDRESS COMPANY / BILLING NA 303 - 908 WEST 7TH AV VANCOUVER , V5Z1C3 BRITISH COLUMBIA, CA	E		SERVICE ADDRESS 303 - 908 7TH AVE. V BUZZER: 12 VANCOUVER , V5Z1 BRITISH COLUMBIA,	C3
PHONE 1.514.296.5037			EMAIL darladimple@hotmail.	com

REASON FOR TODAY'S CALL:

My water tab in the shower stopped working. It seems that some parts came loose. The handle spins around without any resistance and it doesn?t open the water tab any more. The water fossett is from Delta. I was try to take a picture with my phone and send to you but the app keeps crashing. Thank you.

DESCRIPTION OF WORK PERFORMED:

The screw test secures the handle in place worked itself loose. I resecured the handle and tested.

QTY. CODE	DESCRIPTION			PRICE
1	Labour		\$109.00	\$109.00
Company (I	WARRANTY:	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		\$109.00
Gwe us Fe Please visit our feedback		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	GST (5%):	\$5.45
www.yaletownplumbing.c			TOTAL:	\$114.45
<u>Thank You</u>	SETTLED RUS	STED HEREON ARE CORRECT, YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, STED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES ROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK & O. E.		