



HST #837181627

DATE 2018-05-29	TECHNICIAN Darren Mann		JOB/O 8511	RDER #	REFERENCE TEXT Client reference
FIRST NAME Brenda		LAST NAME Chong			
BILLING ADDRESS COMPANY / BILLING NAME 2902 - 833 HOMER ST VANCOUVER, V6B 0H4 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS  2902 - 833 HOMER ST VANCOUVER, V6B 0H4 BRITISH COLUMBIA, CANADA	
PHONE 778.822.2846				EMAIL shingchong@yahoo.com	

## REASON FOR TODAY'S CALL:

kitchen faucet leaking. issues with shower head. \*at work 5 mins away. call when en route.

## **DESCRIPTION OF WORK PERFORMED:**

-The shower head was spraying erratically. I replaced the shower head with a new single function Delta Shower Head and tested. -The kitchen faucet was not leaking while I was onsite. I believe the leak may have been coming from the connection between the spray head and the spray hose. It is possible that this connection was loose but became tight through use. I suggested keeping an eye on it.

QTY.	CODE	DESCRIPTION				PRICE
1		Replace Shower H	lead - Delta		\$129.00	\$129.00
invoice and tell us how we did.  MADE THAT MATERIALS. SETTLED, R RESULTING TERMS: NE		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$129.00	
			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY N		\$6.45	
		WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		TOTAL:	\$135.45	
		MADE THAT MATERIALS SETTLED, RI RESULTING	T THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, USTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  **CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK**  **E. & O. E.**			

CUSTOMER SIGNATURE

DATE