

(a) @SimplyPlumbing **F** YaletownPlumbing

HST #837181627

DATE 2018-05-31	TECHNICIAN Darren Mann		JOB/O 8521	RDER #	REFERENCE TEXT Client reference
FIRST NAME Jonathan		LAST NAME Burns	7		
BILLING ADDRESS COMPANY / BILLING NAME 2305 - 969 RICHARDS ST VANCOUVER, V6B 1A8 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 2305 - 969 RICHARDS ST BUZZER: 2355 MOM: 1.403.831.6924 VANCOUVER, V6B 1A8 BRITISH COLUMBIA, CANADA	
PHONE 1-403-830-9735				EMAIL jon.burns@gmail.com	

REASON FOR TODAY'S CALL:

1. The Bathroom faucet will drip if the cold water line isn't shut off 2. The chain that connects the toilet flush handle to the flapper snapped.

DESCRIPTION OF WORK PERFORMED:

-I replaced the cold cartridge in the Tebisa lavatory faucet and tested. -I installed a new toilet flapper and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Cartridge in 2 Handle Tebisa Lavatory Faucet - Cold	\$159.00	\$159.00
1	11	Kohler Blue Flapper	\$20.00	\$20.00
0		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$179.00
Gwe us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank Youl</u>		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$8.95
			TOTAL:	\$187.95
		Ve did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTIED RUSTED DETERIORATION OR LEAD PIPES EXTIRES CLEAN OUTS AND ANY OTHER DAMAGES.		/

X	
11/2 at at	
1 ANA	2018-05-31
CUSTOMER SIGNATURE	DATE