

(B) @SimplyPlumbing | YaletownPlumbing

2018-06-01

HST #837181627

DATE 2018-06-01	TECHNICIAN Darren Mann		JOB/ORDER # 8542		REFERENCE TEXT Client reference
FIRST NAME Colin		LAST NAME Doig	9/		
BILLING ADDRESS RE/MAX CREST REALTY WESTSIDE 1428 WEST 7TH AVE VANCOUVER, V6H1C1 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 3304 - 1189 MELVILLE ST, BU. PEGEH: 778.317.0993 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.417.9003				EMAIL colin@colindoig.com	

REASON FOR TODAY'S CALL:

Kitchen faucet leaking.

DESCRIPTION OF WORK PERFORMED:

-The leak from the kitchen faucet was coming from the connection between the spray head and spray hose. I tightened this connection and tested. During testing I noticed there was also a leak coming from the garburator that could not be repaired. I replaced the garburator with a new Waste King 1001 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	//	Supply & Install 1/2HP Waste King 1001 Garburator	\$279.00	\$279.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				\$279.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$13.95
		s from your	TOTAL:	\$292.95
		WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CRANGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED BUSTED DETERIORATION OF LEAD DIDES. SUTTINES, CLEAN OUTS AND ANY OTHER DAMAGES.		